Attachment 4 – Site photos



Image 1 – Photo of the garage and hardstand at No. 45 the Circus, Burswood.




Image 2 – Photo of the garage and hardstand at No. 45 the Circus, Burswood.



Image 3 – The Mews access road at rear of dwelling looking back towards adjoining single dwellings.



Image 4 – The Mews access road at rear of dwelling looking towards mixed use development.




Image 5 – Image provided by applicant showing two car bays at rear of existing garage.